	AGENCY FOR INTERNATIONAL DE WASHING FON, D. C. 2082 BIBLIOGRAPHIC INPUT	23		FOR AID USE ONLY	
1. SUBJECT CLASSI-	A. PRIMARY Agriculture		AP12-0000-G355		
FICATION	B. SECONDARY Drainage and irrigation-	-El Salvad	ior		
2. TITLE AND Sub-irri	SUBTITUE Egation in the Zapotitan pr	oject	i		
Griffin,	R.E.				
. DOCUMENT	DATE 5. NUMBER	R OF PAGES	6. ARC NUM	BER	
1971	5p.		ARC	ES631.7.G852	
v. REFERENC Utah Sta	E ORGANIZATION NAME AND ADDRESS				
8. SUPPLEME	NTARY NOTES (Sponsoring Organization, Pu	blishers, Avails	Łilii,)		
. ABSTRACT					

10. CONTROL NUMBER	~	11. PRICE OF DOCUMENT
PN-RAA- 009	, , , , , , , , , , , , , , , , , , , ,	
12, DESCRIPTORS		13. PROJECT NUMBER
El Salvador Subsurface drainage Zapotitan Project		14. CONTRACT NUMBER COD-2167 Res. 15. TYPE OF DOCUMENT

SUB-IRRIGATION IN THE ZAPOTITAN PORJECT

A REPORT BY

RICHARD E. CRIFFIN

TECHNICAL ADVISOR
HINISTRY OF AGRICULTURE
GRANDES OBRAS DE RIEGO Y DRENAJE

EL SALVADOR OCTOBER 1971

CUBLUPICATION IN THE ZAPOTITAN PROJECT

INTRODUCTION

At the request of the Depto. of Irrigation and Drainage studies were made to determine the leasability of Sub-irrigation in the lower portions of the Zapotitan Valley.

The tahal report * suggests sub-irrigation as a possibility for some of the areas within. The valley. Department of irrigation and * Drainage Officials suggested studies be made in the lower area when * the soils are of a finer texture.

OBJECTIVE

in the porposed areas, open drainage channels are constructed on a parallel spacing of about 260 maters.

The objective was to construct dams in the drainage channels and force the water horizontally underground, hopefully at a one meter - depth, from one channel to the next. The stope between channels is about 1/2%.

PROCEDURE

At the beginning of the dry season, in November 1970, earth dams were constructed on many o: the drains throughout the project.

Six observations wells were dug, four were between las canes D-1 and D-2 and two were just below D-2. The soil profiles for wells 2 thru 5 are shown in Fig. 1.

Readings were taken periodically of the depth to water table in the wells. The general condition and growth of crops was also noted.

RESULTS

There was no consistency in the depth to water table in the obser-

vation wells as shown in Table 2 given time the depth to water table varied in the 6 wells. Water was not kept in the drainage channel continually and this also affected the depth.

* Tahal Consulting Engineers Ltd Proyecto de Desarrollo Agricola del Valle de Zapotitan 1970.




Fig. 1 Soil Profiles, between Canas D-1 and D-2, Zapotitan.

Table 1 Depth in cm. to water table in the six observation wells in Zapotitan Valley.

		,		••		
DATE		WELL				•
1970 -	1	2	. 3	. 4	5	6 ·
Oct 13	30	40 ′	50 '	90 '	120	30
Oct 27	•	30,	40	80 ,	30	40
Nov 3	•	20	78 -	80	~ 100 <i>></i>	40
Nov 17	•	40	, ['] 50	80	20 %	40
Dec 15	•	30	60	. 70	100	50

Fig 2 best describes the situation as found in the areas where sub-irrigation is practiced. This picture is typical with wet and dry spots throughout the entire area. This wet end dry spots correspond to the variation in water depth, and also the variation in the soil profiles.

An over riding factor was that some farmers would observe dry spots, such as in Fig 2 from the drainage channel and flood the entire area.

The growth of crops (Beans, tomatoes, potatoes, cucambers and - corn) reflected some what the depth to water table. Areas where the water table was about 50 or 60 cm had the most vigirous growth.

Average agricultural production in the Zapotitan valley during this period was:

Corn	783	lbs/acre
Tomatoes	5.6	tons/acre
Potatoes	5.96	tons/acre
Cucumber	5.05	tons/acre

CONCLUSIONS AND RECOMMENDATIONS

There appears to be three factors which contributed to low production in the Zapotitan Valley. They are: 1) poor seeds (uncertified) 2) Disease and 3) Un even donths to water table. The interalaction of these factors makes it difficult to evaluate production as a result of sub-irrigation.

Sub-irrigation in Zapotitan is not feasable nor practicable for - maximum agricultural production. The soil structure and profile does not allow for even distribution of water in the crop root zone. The - uneven distribution of water supports this.

It is recommended that better means of water control, including adaquate and complete drainage be carefully considered. Without this good agricultural production cannot be expected.