

Putting On Enhanced PPE

For delivery room, isolation areas, cleaning spills

Supplies needed:

- Boots
- Gloves (2 pairs)
- Gown
- Head cover
- Face mask
- Goggles
- Apron
- 0.05% chlorine solution OR hand sanitizer OR soap and running water

1. Remove jewelry



2. Put on boots



3. Wash your hands with 0.05% chlorine OR hand sanitizer OR soap and running water



4. Put on inner pair of gloves.



5. Put on gown.



6. Put on face mask.
7. Put on goggles.
8. Put on hood.



9. Put on second pair of gloves.



10. Put on apron.

